

Status?
DON'T SAY IT — WRITE IT

To J. P. LINDE — F. E. MARTIN

From A. A. HUGICK

Fickett June 15
Date May 12, 1977

Two years ago the XP-100 bolt plug and safety assembly designs were reviewed due to pending impact test of exposed hammer — striker assemblies. The safety has been modified with thumb piece material change — BUT — bolt plug changes have not been implemented. Abuse of the M/600 bolt plug for eliminating an exposed striker should be implemented as soon as possible.

AAH:bd
Measurement/Test Lab
Ilion Research Division

Copies to: C. B. Workman
File

DON'T BE SORRY — BE SAFE