


MODEL XP-100 BOLT ACTION PISTOL



WARNING
DO NOT ASSEMBLE
WITHOUT
Part No. 48 Trigger Balance
& Part No. 50 Trigger Balance Spring

Send all guns for factory service and inquiries on
service and parts to
REMINGTON ARMS COMPANY, INC.
Arms Service Division
Ilion, New York 13357

All other inquiries are to be addressed to
REMINGTON ARMS COMPANY, INC.
Bridgeport, Connecticut 06602