

TEST FOR 600 SAFETY FUNCTION

1/29/75 CP

CHECK FOR NO AMMUNITION!

1. ACK RIFLE, CLOSE BOLT AND PUSH SAFETY BACK TO ON SAFE.
2. PULL TRIGGER - NO CLICK, TRIGGER RETRACTS.
3. PUSH SAFETY FORWARD ABOUT HALFWAY - TRY TRIGGER AGAIN - NO CLICK, TRIGGER RETRACTS.
4. PUSH SAFETY FORWARD SLIGHTLY.
 - a. SAFETY SHOULD SPRING FORWARD TO OFF. FIRING PIN REMAINS COCKED.
5. IF SAFETY DOES NOT SPRING FORWARD REPEAT STEP NUMBER 4.
6. REPEAT TEST 3 TIMES

DESCRIPTIVE INFORMATION




FIGURE 2

PUSH CONNECTOR UPWARD HERE

FIGURE 1

PART NAME _____ COOLANT _____
 TYPE "SCREWDRIVER" TEST @ ASSEMBLY
 CUSTOMER REPAIR

SET UP TIME _____ MODEL No. 700 & 600
 MACH. IIRG _____ DEPT. No. _____
 MACHINE

OPER. No. _____
 PAGE 2 OF 3