

KC:

J.W. BLAIR
G.J. HILL
J.P. LINDE
C.S. ALBRE

K.L. TAYLOR

RE: MXP-100 RECEIVER SIGHT HOLES REWORK

QUANTITY OF RECEIVERS WHICH WERE DRILLED
WITH THE "WRONG HOLE POSITION" ARE TO BE
PROCESSED AS FOLLOWS; WHEN A 0.475" SHIM
IS PLACED AT FACE OF RECEIVER AND A THIRD HOLE
IS DRILLED (IN SAME FIXTURE ON REM. SPEC.), WE CAN
USE THE FIRST 2 HOLES FOR SCOPE MOUNT.
OPERATOR MAY USE A SCOPE MOUNT AS A GAGING GUIDE.

C.S. Pore 11/16/79
J.B. Linde