

ITEM 3

MATERIAL ON MODEL 700 RECALL - 1980

PROBLEM

Some 350 Model 700 rifles were suspected of leaving the factory in January of 1980, having an improperly plated sear safety cam, which could have resulted in the sear safety cam flaking and rusting. Recall, was, by-in-large, confined to contacts with our wholesalers and dealers.