

~~Monthly Report~~
~~Please Contact & Tele ASAP~~
~~Thank You~~

Highlights

Product Development

Model 870 Competition Trap Gun - Problems of barrel

Failure has been solved. Potential solutions to broken locking blocks are in effect. Bolt separation remains a problem.

Bolt Action Carbine - New oil floor plate

latch being developed. Program is still on schedule.

Model 7400 and Model 7000 - Preliminary test

results from mechanical are encouraging.

Model 15 C Shotgun - Major endurance

tests show action opening and closing block bridge pins are still a problem. Design under review.

4700 Bolt Action - The Bolt Action will

be ready for review by marketing and the operations committee in April.

Seismic Gun - Tests show that

firing pin revisions are required. New firing pins will be tested in April.

Auto Drill Line - Machines have

been delivered to Lion and installation has started.

The results of the tests conducted by the
reviewers will prove a most satisfactory
endurance life if the magazines are tight.
However one locking block failed in a safe
manner at 12,700 rounds and vented sub-
ports are still separating from the barrel.