

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
OUPON

PETERS
OUPON

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY" _____

XC: W. E. Ackley
J. H. Carter
W. W. Cook
J. J. Czelusniak
G. E. Fletcher
J. A. Harter
J. P. Linde
D. E. Lonis
L. G. McCumber
C. O. Pardee
D. V. Pearson
R. E. Smith

7/13/81

A. HUFFMAN

M/700 RECEIVERS SERIAL NUMBER INCORRECT PREFIX

A quantity of M/700 Receivers were serial numbered with an "A" prefix instead of a "B". The range of these numbers were A6337820 to 6338936. This is a total quantity of 1,116 Receivers.

This letter is authorization to salvage these Receivers by using a suffix "Z" after the serial number. This will follow the practice of "Suffix Addition to Reported Duplicates" issued by J. J. Czelusniak on 3/10/81.

by

G. J. Hall 7/13/81

G. J. Hall, Supervisor
Process Engineering
Current Products

GJH/cac