

Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: 530

MODEL: 700 BDL

GENERAL CONDITION: FAIR

R # : 24180

OUTSIDE WORK: S/REMOVED, SCOPE MOUNTS ADDED

DATE: 10-9-81

TRIG & CONNECTOR REMOVED AS IS

FROM: BILLY W. SWEAT
PT. 22 BOX 166A
ALLEN TON TEN.

FIRE ARM TYPE: NOT KNOWN

& CONDITION:

GUN # : A6376164

PROOF: 11 INSP.: 123 TEST: 64

CODE: RI-11-76

READING: OK

GA./CAL.: 6MM REM

BREACH OPENING: OK

CHECKED BY: M-HA 900

RECOIL SHOULDERS: OK

APPROVED: 9/28/81

CHAMBER: OK

APPROVED: 10/2/81

TEST: CHECKED FIRE PIN PROTRUSION, OK

APPROVED: 10/2-81

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED:

TRIG. CONNECTOR BROKEN

COMPLAINT: FIRE WHEN TAKEN OFF SAFETY

INCIDENT:

COMMENTS:

Please replace fire control - no charge

501