SAFE "OFF - ON" FORCES

PROCEDURE FOR MEASURING SAFE "OFF - ON" FORCES

1. General

To measure Safe "Off - On" forces on firearms not manufactured by Remington Arms, Consult Lab Supervision.

- 1 A. Equipment Needed (Fig. 4 9)
 - Push pull gauge.
 - Test Procedure Sheet.
 - Work Bench with a Gun Saddle.

Figure 4-9



- 5 -

.