

PS16344

HERBERT J. BEIL, M.D.
658 WEST MARKET STREET
LIMA, OHIO 45801
PHONE 229-0816

RECEIVED

MAR - 7 1965

E. F. JENKOWICZ

March 1, 1965

Remington Arms, Inc.
Arms Service Division
Ilion, New York 13357

Attn: Mr. Sinkowicz, Product Service

Dear Mr. Sinkowicz,

No doubt, you will recall the conversation about the firearm model 700LH, 7 mm. Remington Magnum #B6532467. The initial problem with the gun was that the bolt would not extract the cartridge out of the chamber. The gun was taken to the authorized gunsmith in Bellefontaine and the extractor exchanged. That problem was then rectified.

I have noted that the bolting handle does not stay in the locked down position when the selector is on safe. This has caused multiple inadvertent openings of the bolt with loss of some rounds (until I improvised with a rubber band around the trigger guard onto the bolt handle). Needless to say, this is not a very acceptable solution.

I will be returning the firearm care of Burly's Gunshop (located at Lewis Blvd. in Lima, Ohio). I trust you will be able to rectify the situation.

Sincerely,

Herbert J. Beil, M.D.

P.s. If it is going to be necessary to have a new barreled action, I would prefer 26" instead of 24" barrel. I did like the stock very much, and since it is slightly scratched would prefer to keep it.

rk

Dictated, bmr