REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Reminster.

PETERS

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"_

cc: W.H. Coleman, II
J.W. Bower
K.W. Soucy
G.J. Hill
D.J. Anderson
L.B. Bosquet
J.R. Snedeker
D.S. Findlay
R.E. Nightingale
F.L. Supry
File

RESEARCH TEST AND MEASUREMENT REPORT

REPORT# 850745 MARCH 14,1985

MODEL 700 CLASSIC 350 REM MAG VISUAL INSPECTION

REPORT# 850745

WORK ORDER# G-0460-000 DATE: MARCH 14, 1985

TO: R.E. NIGHTINGALE

FROM: F.L. SUPRY

TITLE: VISUAL INSPECTION: MODEL 700 CLASSIC 350 REM MAG

ABSTRACT:

On March 13, 1985 a request was received to conduct a Visual Inspection evaluation on the Model 700 Classic rifle, chambered in the 350 Rem Mag caliber. Ten (10) rifles were randomly selected from the warehouse.

SCOPE OF TEST:

To determine if the production run samples meet the Remington Specifications set by the Research Design Section.

TEST RESULTS:

The ten (10) rifle Visual Inspection was found to be unacceptable, due to the following:

A. Rifle #B6680586:

a. When the bolt was removed from the receiver, it could not be reassembled, due to a cross pin protruding from the bolt head.

B. Rifle #B6680598:

a. The underside of the stock, just shead of the floor plate assembly, was cracked.

COMMENTS:

G.J. Hill took rifle #B6680586 to production, for further examination. All ten (10) rifles were returned to G.J. Hill. Upon the completion of a new sample, another Visual Inspection will be conducted.