

Remington.



REMINGTON ARMS COMPANY, INC.

TELEX
964-201
STRATFORD, CT

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

939 BARNUM AVENUE
P.O. BOX 1939

TELEPHONE
203-333-1112

BRIDGEPORT, CONNECTICUT 06601

April 7, 1984

Dear :

Remington has contacted and informed you about the problem that may develop with your Model Seven rifle, and you have refused to return the firearm to us for correction. By sending you this letter, we want to be sure you clearly understand that if your Model Seven is disassembled for any reason, the rifle may possibly be re-assembled incorrectly which could produce an off-center trigger alignment that may cause subsequent malfunction of the trigger and accidental firing of the rifle.

We strongly suggest you return your Model Seven to Remington or to a Remington warrantee gunsmith service location for no charge updating. The preventive modification will then eliminate the possibility of an incorrect re-assembly. However, we cannot correct the rifle if you do not return it to us, or to our agent, for updating.

It is always possible that you will loan your Model Seven to a family member or sell it to a friend or to some other third party sometime in the future. Since you have been adequately warned about the potential danger in your gun and have consciously determined not to take any corrective action, you could be held responsible and legally liable for any problem or injury that may arise in the future from disassembly and incorrect re-assembly of the rifle.

We now urge you to reconsider your decision in the interest of safety, and allow us to eliminate this potentially dangerous condition in your rifle.

To accomplish this necessary modification, we request that you bring or ship your Model Seven rifle to the nearest Remington warrantee gunsmith service location in your area. A list of such locations is enclosed.

R2517563

If it is inconvenient or difficult for you to return the rifle to a warrantee gunsmith service location, you may also ship the firearm, via United Parcel Service, transportation C.O.D., to:

Remington Arms Company, Inc.
Arms Service Division
Ilion, NY 13357

In returning your rifle to either a Remington warrantee gunsmith service location or to our Arms Service Division in Ilion, New York, please do the following:

1. Mark the outside of the box clearly with the words "Model Seven".
2. Include your name and return address on the outside of the box and on a note to be placed inside the box.

These procedures will expedite the updating of your rifle and its return to you.

If you need a box for shipping purposes, please advise me at the Bridgeport, Connecticut address.

Should you have any questions about the Model Seven update, you may call me collect at the following number:

203-333-1112 Ext. 1429
(8:00 a.m. - 4:30 p.m. EST)

Our apologies for any inconvenience this return may cause you. Thank you for your cooperation in this important matter.

Sincerely,

K. D. Green
Manager, Product Support

KDG:fd

enc.

RBS
5/4/8