



Asash Termite & Pest Control

"For Making Laredo an Even Better Place to Live"

1102 CLARK BLVD.

LAREDO, TEXAS 78040

724-8125



RECEIVED

MAR 16 1983

J. A. STEKL

March 14, 1983

J. A. Stekl, Supervisor
Firearms Product Service
Remington Arms Co.
Ilion, New York 13357

Dear Mr. Stekl,

I received your letter of February 23, 1983, and need to once again make reference to my previous letter.

I realize that you can not diagnose the problem without examining the rifle, and I intend to send it as soon as some very important points are clarified so you can rule out some of the possibilities that you enumerate in your letter.

Most important is that the rifle fires sometimes after moving the safety from safe to fire repeated times.

This has happened to me after deliberately moving the bolt and safety countless times back and forth until the rifle has fired.

I want you to be aware of these facts and send me further instructions so that I can take the necessary action.

Your truly,


Henry B. Fernandez, Jr.

HBF/ca