

RECEIVING AND ESTIMATING REPORT ✓

INITIAL LCS		CUSTOMER ORDER NO. 87563		COMMENTS 64			
DATE RECEIVED 11/29/91	DATE OPENED 02/05/91	DATE CODE EE 10-84	SERIAL NUMBER B6639409	MODEL AND GRADE 700 30-06.1 BDL		ORDER R 91-0364	
ACCESSORIES W/STUDS							

FROM: AHLMAN'S ROUTE 1 BOX 20 MORRISTOWN MN 55052		SHIP TO: AHLMAN'S ROUTE 1 BOX 20 MORRISTOWN MN 55052	
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST
		PROM. DATE	ESTIMATED 2-13-91
		VIA UPS	

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:	☐ NEW	☒ SLIGHTLY WORN	☐ VERY WORN	☐ MISUSED	☒ MARRED
----------------	------------------------------	---	------------------------------------	----------------------------------	--

CUSTOMER'S REQUEST: Fired when closing bolt, safety sticks

for evaluation
Sent to J. Stekl

MAIN FAULT: No fault found - cannot duplicate complaint.

suggest safety assembly operator properly. Trigger pull 5 1/2 #; rest - left 0.015"

butt of stock marred several places, trigger guard scratched

offer to return rifle as-is or, we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.

REPAIRMAN 64	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90