

TTT-27

american service company  
of atlanta, inc.

C. EVERETT THOMAS, JR.  
PRESIDENT

20 November 1981

Sportco, Inc.  
1696 Cobb Parkway, S. E.  
Marietta, Georgia 30062

Subject: Remington Model 700BOL  
Serial Number A666 3581  
Purchased 11 August 1981

Gentlemen:

Please be advised that the subject rifle purchased from your firm has a very dangerous defect. The rifle will discharge when the safety switch is moved from the safety position to the fire position, and it will discharge when the bolt is moved to clear cartridges from the chamber and clip.

I am not sure whether or not the aforementioned malfunctions occur every time the situations outlined exist, or if they are intermittent problems. In any event, I am sure that you will agree that they are very dangerous, and I would like them repaired, or the rifle replaced, and a written statement that the repairs have been made.

By copy of this letter I am putting the manufacturer on notice of these problems.

Cordially yours,

AMERICAN SERVICE COMPANY OF ATLANTA, INC.

C. Everett Thomas, Jr.  
President  
CET/bbr

cc: Mr. Gregory W. Sturgeon, Attorney at Law

2006 Weems Road / Tucker, Georgia 30084