

Liability Waiver

August 28, 2008

Dear Mr. Basarich,

We have received the following firearm: Model 700 .204 Ruger, Serial number S6543693.

We have examined your firearm and determined that the Fire Control Mechanism (Trigger Assembly) is in need of repair or replacement due to adjustments made outside the factory. In its current condition we feel that the rifle cannot be operated in a safe manner and should not be used. As such, we recommended to you via repair # 148765 that we replace the Trigger Assembly. We offered to install the new Trigger Assembly at a reduced price.

You have decided not to have us replace the Trigger Assembly but have requested that your original be returned to you in its current state. We will return it with the firearm provided that you sign this document verifying that:

- You were presented with an opportunity to have the Trigger Assembly replaced.
- You understand that it is Remington's opinion that the firearm is currently not in a safe condition.
- You have been informed by Remington that the firearm should not be used until the Trigger Assembly is properly repaired or replaced by a Remington Authorized Repair Center or by Remington Arms Company, Inc.

Sign below:

Steven Basarich