
From: Watson, Laura M.
Sent: Monday, January 15, 2007 9:11 AM
To: Supry, Fred L.
Subject: RE: Two ARS labels

Will do. thanks

From: Supry, Fred L.
Sent: Friday, January 12, 2007 3:21 PM
To: Watson, Laura M.
Subject: Two ARS labels

1/12/2007

Please send two ARS labels to:

Michael Miller
5144 Chateaugay Drive
Mason, OH 45040

1. While cycling his reloads through his rifle he had one go off – He was in his cellar and it shot through the floor above him, through a table, and wall. He is ok except for some ringing in his ears and a minor bruise on his leg where the stock was resting. He said he went on the internet and found out that Remington has a problem with these rifles. I explained that there is usually an underlying issue, i.e., improper maintenance, alterations, etc. Date of incident was 1/6/2007. Model 700 rifle with the bolt lock style safety.
2. He has a Model 722 that he would like to return for the bolt lock modification program. No issues with this gun – just would like to be able to load and unload with the safety on.

His phone # is 513-398-5998.

Fred Supry, Manager
Product Service and Law Enforcement Training
Remington Arms Company
14 Hoefler Avenue
Ilion, NY 13357

Phone: 315-895-3606
Fax: 315-895-3661
e-mail: fred.supry@remington.com