



03 December 2008

Stuart Black
PO Box 1508
Hayesville, NC 28904

RE: Model 700 BDL
Serial #: A6512253

Dear Stuart,

Your letter was forwarded to my attention. The rifle that you purchased was produced in Ilion, NY on 11 October 1977. There is no recent history of this rifle coming back to the factory for any repairs. The rifle most likely has the bolt lock system (which means the safety has to be in the ready to fire position in order to work the bolt.) If that is the case, we offer a bolt lock modification program – where you send the rifle in to Arms Service in Ilion, NY and we would check the rifle over completely, clean the action, and change the trigger mechanism so that the bolt would operate in either the safe on or safe off position. The cost for that service is \$20 plus shipping for a total of \$35.00. This would be a good opportunity to have the rifle completely checked out for a minimal cost. If you choose to send the rifle, send it to the Remington address below with a note inside the shipping box indicating that you would like to have the rifle checked and take advantage of the bolt lock modification program.

The magazine capacity is three rounds. If only two go into the magazine, someone may have disassembled the unit and reassembled it incorrectly. We do not offer any retrofit to change the system to a detachable magazine. There may be some after-market systems available but I don't know who would currently offer this service. I will enclose a copy of a Model 700 owner's manual.

Sincerely,

Fred Supry, Manager
Product Service and Law Enforcement Training
Remington Arms Company
14 Hoefer Avenue
Ilion, NY 13357

Phone: 315-895-3606
E-mail: fred.supry@remington.com

Remington Arms Company, Inc. • 14 Hoefer Avenue • Ilion, NY 13357
Phone 315-895-3200 • www.remington.com