## **BARBER - RE 0000561**

From: Supry, Fred L.

Sent: Thursday, May 25, 2006 11:37 AM

To: Nickerson, E. Ken

Subject: RE: Member requests information - Remington 700 rifle problems

I sent an e-mail back to D Wayne Pickett asking him to send the rifle to my attention for examination and repair.

On the other problem of internet bashing, what kind of information would you suggest? We have rifles come back for this concern and there is usually some problem that created the incident. Most of the time is either improper adjustment or improper cleaning and maintenance.

Fred Supry, Manager Product Service and Law Enforcement Training Remington Arms Company 14 Hoefler Avenue Ilion, NY 13357

Phone: 315-895-3606 Fax: 315-895-3661

e-mail: <u>fred.supry@remington.com</u>

From: Nickerson, E. Ken

**Sent:** Thursday, May 25, 2006 11:29 AM

To: Supry, Fred L.

Subject: FW: Member requests information - Remington 700 rifle problems

Fred, we need to have some information to post for these guys.

From: Cockman, Mark T.

**Sent:** Thursday, May 25, 2006 11:16 AM

To: Felter, Brian A.; Johnson, Rick W.; Lowitz, Steve; Minichino, Benjamin; Sevall, George W.; Foster, Greg; Haugen,

Michael

Cc: Nagle, Thomas J.; Nickerson, E. Ken

Subject: RE: Member requests information - Remington 700 rifle problems

I have had a \*#%@ storm of rumor problems like this in the NW since 2004. It has cost us a good portion of the sniper market up there. I have written letters, talked to agencies, and its been one dam break after another.

I understand from all of my discussions that this is ONLY possible when the trigger is messed with. I know of no situation of this occurring (for certain) with a trigger that has not been modified. This kind of email circulates like wildfire and is taken for gospel as is most anything on the net.

It needs to be clarified with us, from someone like Tom Nagle, have we ever had issues with 700 triggers doing this that haven't been messed with????

Then, perhaps we should put something on the webpage discussing it, I would be happy to compose.

From: Felter, Brian A.

Sent: Thursday, May 25, 2006 8:48 AM

To: Johnson, Rick W.; Cockman, Mark T.; Lowitz, Steve; Minichino, Benjamin; Sevall, George W.

Subject: FW: Member requests information - Remington 700 rifle problems

Hi Guys,

Anyone seen this?

1

## **BARBER - RE 0000562**

Brian

**From:** Rogers, George C [mailto:George.C.Rogers@dhs.gov]

**Sent:** Thursday, May 25, 2006 8:44 AM

To: Felter, Brian A.

Subject: FW: Member requests information - Remington 700 rifle problems

Brian - this came across my screen - anything to it we should be aware of?

Butch

## From: Pickett, D Wayne Reply directly to: <u>DWayne.Pickett@cobbcounty.org</u>

Sent: Wednesday, May 24, 2006 12:43 AM

To: Williams Mike

Subject: Remington 700 rifle problems

Mike,

Have you had or heard of any recent issues involving the Remington 700 bolt action rifles. Our team currently has eight counter snipers who are utilizing the Remington 700 Light Tactical Rifles (.308). Last year one of the rifles malfunctioned and fired when the sniper moved the safety lever from the "safe" position to the "fire" position without touching the trigger. We had our second malfunction during training during the month of April 2006 with a second rifle. I know there have been previous investigations into this issue Remington and the company basically related the problems only exist with rifles manufactured prior to 1975. Both of our rifles were purchased in the last five years. The first rifle was returned to Remington who related the problem was corrected and possibly caused by "internal cleaning issues". We are currently weighing our options with the second rifle which has been "grounded" from service. Due you have any in-sight reference to this issue?

Any help would be appreciated!

Thanks,

Sgt. Wayne Pickett Cobb County P.D. SWAT 770-499-3970

Cobb County...Expect the Best

## www.cobbcounty.org

This Email has been scanned for Viruses and Spam by an E500 McAfee Engine