

NOTICE:

The rifle stock may need modification for proper fit with the X-Mark Pro trigger system.
Check for proper clearance for the safety arm mechanism.

The safety arm should not rub the inside of the stock. If there is any interference
clearance will need to be cut into the stock.