

---

**From:** Perniciaro, Stephen  
**Sent:** Friday, March 14, 2008 6:09 PM  
**To:** Ronkainen, Jim  
**Subject:** FW: 700 XMP Updated Sear Verification  
**Attachments:** 700 XMP Updated MIM Sear Verification 20080006 031208.pdf

FYI

Steve

---

**From:** Joy, Robert L.  
**Sent:** Thursday, March 13, 2008 10:40 AM  
**To:** Becker, Craig  
**Cc:** Perniciaro, Stephen; Orf, Robert J.; Shoemaker, Christopher D.; Doolittle, James F.; Farrington, Kenneth L.; Marley, Matthew M.  
**Subject:** 700 XMP Updated Sear Verification

Craig,

Here is the verification test report on the recently updated MIM sear design that was done to eliminate possible bolt bind issues. The components you submitted passed all of our test successfully. Let me know if you have questions.

*Bob*

*Robert L. Joy*  
*Staff Engineer*  
*Supervisor - Test & Measurements Lab*  
\*\*\*\*\*  
**Remington Arms Company, Inc.**  
*14 Hoefler Avenue*  
*Ilion, NY 13357*  
Phone: (315) 895-3371  
Fax: (315) 895-3670  
e-mail: [bob.joy@remington.com](mailto:bob.joy@remington.com)