

3-3/528-333

P.I. 155 GUN EXAMINATION REPORT NUMBER: 5 - MODEL: 660
 GENERAL CONDITION: USED R #: 16659
 OUTSIDE WORK: SCREW DRILL - 1/8" DATE: 1-1-71
 FROM: BOB BAKER
 FIRED AMMO TYPE: 7.62 NATO 5000 COLON
 & CONDITION: GOOD GUN #: 12532
 PROCP: 950 INSP.: 74 TEST: 36 CODE: PL-2-64
 HEADING: 04 GA./CAL.: 222
 BREACH OPENING: 04 CHECKED BY: 11-1-000
 RECOIL SHOULDERS: 04 APPROVED: 5/1/71
 CHAMBER: 04 APPROVED: 5/1/71
 TEST: 04 APPROVED: 5/1/71
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 5/1-18

SLIGHT DETAIL WORK - 1/8" - 1/4" - 1/2" - 3/4" - 1"

1/8" - 1/4" - 1/2" - 3/4" - 1"

COMPLAINT: FIRE WHEN BOLT IS LOCKED
FORWARD
 INCIDENT:

COMMENTS: Serial 1007. Gun & Safety cam has
sluggish action due to gummy substance on these
parts. This condition could have contributed to incident

Replace trigger assembly.

W/180