

---

**From:** John Klein [jksniper@optonline.net]  
**Sent:** Tuesday, July 11, 2006 1:29 PM  
**To:** snipersonline@list1.netnet.net  
**Subject:** Re: [snipersonline] Remington Trigger Article  
**Attachments:** message-header.txt; message-footer.txt

Quote from the article:

"According to an internal Remington memo, the actual sequence required to make a gun malfunction, or "trick," is to place the safety between the "safe" and "fire" positions, pull the trigger, and then place the safety in the "fire" position - which causes affected guns to fire. I can't make my model 700 fire in this manner, but it is allegedly possible."

I think that this is indicative of an operator problem rather than a problem with the weapons system.

John Klein

----- Original Message -----

**From:** Brian K. Sain  
**To:** Snipersonline  
**Sent:** Tuesday, July 11, 2006 11:37 AM  
**Subject:** [snipersonline] Remington Trigger Article

--DO NOT FORWARD electronically or through printed text--

--All material is the intellectual property of the author and/or Snipersonline UA. Copyright restrictions apply.--

---

[http://hunting.about.com/od/guns/a/aacbsnewsrem700\\_2.htm](http://hunting.about.com/od/guns/a/aacbsnewsrem700_2.htm)

---

Yahoo! Messenger with Voice. [Make PC-to-Phone Calls](#) to the US (and 30+ countries) for 2¢/min or less.

---

--DO NOT FORWARD electronically or through printed text--

--All material is the intellectual property of the author and/or Snipersonline UA. Copyright restrictions apply.--

---

This Email has been scanned for Viruses and Spam by an E500 McAfee Engine