

misfiring rifle

Discussion Thread

Response (Howerton) 4/7/2006 11:45:08 AM

Safety Modification Program

Remington Model 700 & Model 40-X

If you own a Remington Model 700 or Model 40-X rifle:

Only those Model 700 or 40-X rifles made before March 1982 were manufactured with a bolt-lock mechanism. Model 700 or 40-X rifles made after March 1982 do not have a bolt-lock mechanism and may be loaded and unloaded with the safety in the S or On Safe position. Consequently, post-1982 Model 700 or 40-X rifles are not subject to this bolt-lock Safety Modification Program.

If your Model 700 or 40-X rifle has a bolt-lock mechanism, it is eligible for this bolt-lock Safety Modification Program. If you participate, your firearm will be cleaned and inspected for proper functioning by a qualified gunsmith. Once the condition of your firearm has been assessed, you will be notified of one of the following:

Your firearms trigger assembly is otherwise in good operating condition, and the gunsmith will proceed to physically remove the bolt-lock feature so that your rifle can be loaded and unloaded while the safety remains in the S or On Safe position; or

Your rifles trigger assembly is found to be in an unsatisfactory or potentially unsafe operating condition because of any number of factors, including wear, alteration or maintenance. The entire trigger assembly will be replaced with a new factory trigger assembly, which does not incorporate a bolt-lock mechanism.

In either case, the total cost to you is \$20, shipping and handling. You will also receive a safety redemption certificate to complete and submit in order to receive a free blaze orange hat (one hat per certificate).

How to participate in the Safety Modification Program

Complete the General Repair Form and

Send or deliver your firearm and the completed repair form to either:

- a) A Remington Authorized Repair Center; or
- b) Ship your firearm to the Remington factory at:

Remington Arms Company, Inc.

Ilion Firearms Plant

Attention: BL Safety Program

14 Hoefler Avenue

Ilion, NY 13357

Remington will bill or arrange for payment once your firearm is received and evaluated.

CAUTION: It is your responsibility to comply with all laws and regulations regarding transportation or shipping of your firearm. Absolutely no ammunition should be packaged with the firearm whether loaded in the firearm itself or included in the shipping container. The firearm should be transported only in a completely unloaded condition.

No matches were found.

Customer (Bunky loucks) 4/6/2006 8:56:06 PM

I have a model 700bdl chambered in Rem. 270 that went off during a hunting trip last fall when my 14 yr. old was opening the action with a live cartridge in the chamber. he said his finger was not in the trigger guard, but I was not sure what to believe because he is such a novice. I was talking to a friend and he said I should contact Remington because he had heard of this problem.

the gun's serial # is A66351XX.

do we have a porblem gun?

BARBER - RE 0011671

please advise,
Bunky Loucks
Casper, Wyoming

BARBER - RE 0011671

RE0011611