

## BARBER - RE 0011748

Rem 700 Safety issues

Discussion Thread

Response (Chris) 7/16/2007 6:11:53 AM

Dear Sir/Madam,

Thank you for contacting Remington Country. We would recommend taking the firearm to a Remington Authorized Repair Center for inspection. With what you have described, we would probably replace the trigger if the condition of your trigger is beyond cleaning or repair. The repair center can inspect it and advise whether the standard removal of the bolt lock with fix the problem or if it should be replaced and they can advise of any charges.

To find your nearest Remington Authorized Repair Center, go to:

[http://www.remington.com/support/repair\\_services/](http://www.remington.com/support/repair_services/)

Customer (Jacob Calkins) 7/15/2007 10:29:51 PM

Can the bolt locking mechanism on pre-1982 Remington 700 ADL/BDL models cause unintentional discharge?

I read up on the retrofitting of the bolt locks, but I don't know if that will solve the other problem I have with my old 700. It has discharged upon disengaging the safety before and if the retrofit won't fix that problem, I'm probably going to take it to a smith to get it taken care of first since it's the more dangerous of the two

BARBER - RE 0011748

RE0011688