

**BARBER - RE 0011764**

Modle 700 30-06

Discussion Thread

Response (Norm) 11/28/2007 12:25:30 PM

Dear Kevin:

Thank you for visiting Remington Country. According to the information that you provided, your Remington Model 700 was produced in or around 1981. We do not have production totals for specific calibers. The Model 700 was introduced in 1962 and is still in production today. This model is widely recognized as the QUOTEmost accurate out of the box production rifleQUOTE on the market today. We would suggest that you review the information found on our homepage in the Safety Center entitled Bolt Action Safety Message: Safety Modification Program for certain pre-1982 rifles .

Customer (Kevin Zane) 10/23/2007 1:07:09 PM

The ser. number for this gun is B6301347

Customer (Kevin Zane) 10/23/2007 4:55:51 AM

I have a remington model 700 30-06. I found it hard to believe with safety being number one in guns and hunting that I have to take the safety off in order to unload the gun. Is this normal or is there a problem with my gun? Is there a modification to make this repair? My gun discharged this weekend when I pushed the safety forward to unload. Thank God I had it pointed in a safe direction. And no, my finger was not on the trigger. I have been around guns all of my life and have been hunting for 38 years. Please respond.

**BARBER - RE 0011764**

RE0011704