

BARBER - RE 0011798

safety issue for Model 700 30-06

Discussion Thread

Response (Chris) 7/14/2008 6:04:40 AM

Dear Mr. Witcher,

Thank you for contacting Remington! We would recommend that the rifle come into the factory for inspection if it has fired on closing the bolt. Complete the factory repair form found at the following section of our site and include it with the rifle. Instructions for shipping a firearm are also on this form. You can call 800-243-9700 1-2 weeks after shipping the rifle for an update. If you include an email address on the repair form they will update you by email.

http://www.remington.com/support/repair_services/

Customer (Andrew Witcher) 7/13/2008 11:20:59 AM

How can I get a replacement part for an old 30-06 rifle my uncle gave to me? He told me to go on the Remington website and find information on a warranty replacement part to resolve an issue of the round going off when you close the bolt. He said this was an issue that you all resolved with a different part for the triggering mechanism. Please advise. Thank you.

BARBER - RE 0011798

RE0011738