

## BARBER - RE 0011804

Feedback for Answer ID 333 (Rated Helpfulness: 75%)

Discussion Thread

Response (Pete) 11/26/2008 6:23:32 AM

Dear Sir,

Thank you for visiting Remington Country. We apologize for the delay in our response. This is the busiest season for us in many years and we are buried under in emails. A computer glitch caused your inquiry to get kicked out of the regular lineup of emails thus the delay.

Sir here is the information you have requested.

[http://www.remington.com/safety/safety\\_center/safety\\_modification\\_program/](http://www.remington.com/safety/safety_center/safety_modification_program/)

Thank you,

Pete

Customer (. .) 11/16/2008 6:06:56 AM

This feedback is about:

[http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup\\_adp.php?p\\_faaid=333](http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup_adp.php?p_faaid=333).

What years of Model 700 need to be considered for bolt replacement? I have a 264 mag 1963-64 it has discharged when the bolt was thrown- It has not done it since I replaced the trigger. Is the safety still jeopardized because of the bolt?