

BARBER - RE 0011805

Safety on model 700

Discussion Thread

Response (Marcus) 12/3/2008 3:09:15 PM

Leland,

Thank you for your email.

This is not a common problem and would be caused by having the trigger adjusted. I strongly recommend you not use this gun until it is looked at by a Remington authorized gunsmith. I have attached links below to a factory repair form as well as a listing of authorized repair centers across the country. Again, I strongly advise you to not use this gun and get it to one of our factory authorized repair centers or back to our factory as soon as possible.

http://www.remington.com/support/repair_services/

http://www.remington.com/support/repair_services/factory_repair_form.asp

Customer (Leland Madsen) 11/24/2008 5:16:31 PM

I have a Remington model 700 Sendero SF, serial No. S6487037. When firing the bolt will jamb until I put the safety in safe position. Then I can eject the shell and load another. When I move the safety to the fire position the gun fires. It about ripped my thumb off. Is this a common problem or should I have a gunsmith look at it. I did have the trigger pull set to 3 lbs. Could that be the problem?