

BARBER - RE 0011818

Repair Order Number RE00157920

Discussion Thread

Response (Ron) 2/17/2009 8:32:35 AM

Dear Ronald,

Thank you for visiting Remington Country! We certainly appreciate you taking the time to write in with your question. We do not know who altered it but according to the repairman it was altered. And the new trigger will include a new safety switch.

Should you have additional questions, please feel free to contact our Consumer Services Department at 800-243-9700, 9:00 am - 5:00 pm, EST, Monday through Friday

Customer (Ronald Hoffbauer) 1/28/2009 8:57:29 PM

I received the quotation estimating report for my model 700. I will sign and return the form as I want the repairs done. However, I would like to ask a question so that I understand what will be done.

Under Technician's Comments I note the Problem Notes. The notes that the Technician could not duplicate the problem I experienced of having the gun discharge when moving the safety switch from S to F in order to unload. The notes indicate QUOTESafety switch altered and will jar offQUOTE. Does this indicate that a previous owner altered the safety switch?

The notes indicate that the trigger assembly will be replaced. Does this include a new safety switch will be installed? If not, will I have to take the gun to a

I look forward to your response.

Ronald Hoffbauer

===== image File Attachment =====
parchment.jpg, 24666 bytes, added to incident

===== image File Attachment =====
imstp_animation_butterflies_en_020908.gif, 31851 bytes, added to incident

BARBER - RE 0011818

RE0011758