

RECEIVING AND ESTIMATING REPORT ✓

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
LCS		2715					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	BDL	ORDER	
11/08/90	11/08/90	DE 7-84	B6603814	700 7HMMAG	BDL	R 90-294	
ACCESSORIES W/STUDS							

L/ REAR SIGHT

FROM:

BARTS SPORTS WORLD
6814 RITCHIE HWY.
GLEN BURNIE MD 21061

SHIP TO:

BARTS SPORTS WORLD
6814 RITCHIE HWY.
GLEN BURNIE MD
21061

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					12-3	UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

discharged twice while taking the safety off,
cart. #2 will not retain in the mag. when cart. #1
is being ejected
cannot duplicate complaint, however, the safety "off" force is
higher than normal.

PARTS

1) Because of higher than normal safety
"off" force, replace trigger assembly
with no-charge

2) Check rifle for proper feeding - make
any necessary corrections

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7