

Some splitting of fore-ends has occurred during assembly of the new self-tapping fore-end bushing. Consideration is now being given to fastening the bushing to the steel fore-end reinforcement. It is expected that the solution to this problem will be established by October 1.

REDACTED  
PRIVILEGED

Legal advice regarding patent listing on guns.  
ATTORNEY CLIENT—WORK PRODUCT

In accordance with a recommendation from Sales, the committee took the following action:

Decision:

The Operations Committee (Arms Division) approves the marking of firearms with the number of the most significant applicable patent followed by the words, "and others."

MODEL 760

244 Remington

The Plant reported that 78 pilot guns have been assembled, but that gallery testing has developed excessive feeding malfunctions. Plant Process Engineering and Research and Development are concentrating on this problem, and expect a solution by September 7. On the assumption that a satisfactory solution will be achieved by September 7, the following warehouse schedule was submitted:

REDACTED