

January 3, 1958

Results Continued

<u>Gun No.</u>	<u>No. of Malif.</u>	<u>Rate</u>	<u>Type</u>
700089	2	.6%	2 Stem chambers (The floor plate on this rifle fell out at 220 rds.)
700085	None		
700227	6	1.8%	6 Stem chambers
700061	None		
700134	None		
700086	1	.3%	1 Stem chamber
700100	3	.9%	3 Stem chambers

Accuracy Test

700061	---	1.85"
		1.25"
		1.7 "
Avg.		<u>1.6 "</u>
700085	---	2.7"
		1.2"
		1.7"
Avg.		<u>1.9 "</u>
700100	---	1.7"
		1.2"
		1.45"
Avg.		<u>1.45 "</u>
700227	---	1.8"
		2.3"
		2.3"
Avg.		<u>2.1 "</u>
700065	---	1.6"
		1.2"
		1.9"
Avg.		<u>1.6 "</u>

700096	---	1.5"
		2.5"
		1.5"
Avg.		<u>1.5 "</u>
700086	---	1.6"
		1.4"
		1. "
Avg.		<u>1.3 "</u>
700134	---	3.45"
		1.3"
		1.8"
Avg.		<u>2.18 "</u>
700089	---	1.2"
		1.5"
		1.4"
Avg.		<u>1.3 "</u>
700070	---	.3"
		1.4"
		2. "
Avg.		<u>1.2 "</u>

83