

I N D E X

ILION DIVISION
MINUTE NO. 3, 1959
May 5, 1959

<u>Subject</u>	<u>Summary</u>	<u>Page</u>
<u>POWDER-ACTUATED TOOLS</u>		
<u>STUD DRIVERS</u>		
3/8" Captive Stud Driver Piston	Items heat-treated to correct observed guide tube breakage.	13
Flush Driving Piston - 1/4" Captive Stud Driver	Items in warehouse stock.	
M/440 Heavy Duty Replacement Piston	Dropped from agenda.	
Model 455A Fire Control	New sear block (for increased protection against drop-firing) demonstrated and described. Committee approves (1) addition to new M/455A production, and (2) installation on all M/455 and M/455A tools returned to Ilion for repair.	13-14
M/430 Hammer Drive Tool and Studs	Market Development studying advisability of adding Hammer Drive Tool and Studs to our line. Item dropped from agenda until ready for report. Star Hammer Drive Tool shown.	14
<u>STUDS</u>		
Iridescent Coating for Studs	Proposal for iridescent coating withdrawn due to costs involved and poor coating quality of samples from vendor. Other coating possibilities being investigated.	15
<u>INDUSTRIAL TOOLS</u>		
<u>STUNNERS</u>		
Model 412 One-Hand Stunner	Parts delivery has delayed assembly until May 15. Tools to be available for shipment in latter part of May, if testing is successful.	15
Extractors - Model 411B Stunner	Cost studies expected in two weeks. Item dropped from agenda. The plan for modifying tools in the field is to be implemented by Sales.	15