

Remington Arms Co., Inc.
10765 Kingspoint Rd
Hudson, N.Y. 10725
Remington Arms
 ATTN: Service Dept
Tioga, New York 13357

-554077

E.F. Barrett
 J.E. Preiser
 E.G. Larson
 R.B. Sperling
 J.H. Chisnall
 D.J. Sanica
 S

RETURN REQUESTED

DATE

JAN 27, 1981

9, 1981

PAIR DEPT.

THE FOLLOWING MERCHANDISE IS RETURNED TO YOU PREPAID.
 UNDER WARRANTY, FOR REPLACEMENT OR REPAIR, AT NO COST.
 THE AMOUNT OF \$_____ IS ENCLOSED FOR HANDLING
 CHARGES AS REQUIRED.

PURCHASE DATE

G. # 700 ARTICLE 3006 Bullseye Rifle
Final while releasing the safety. Fire was
it on trigger. SN# A6919770

I DESIRE THIS MERCHANDISE BE RETURNED TO ME AT THE FOLLOW-
 ING ADDRESS, WITHOUT DELAY:

TURN TO Post Products Co. Inc.
 ADDRESS 10765 Kingspoint Rd
 CITY & STATE Hudson, N.Y. 10725
 TELEPHONE 1-713-460530

S. Mr. Larry Puccetti,
 A6818730, which you
 sety was moved to the

of 1979, has been ex-
 it contained our high-
 precision stampings, in-
 necessary tests prior

good and, in going over
 ml. recoil shoulders

VERY TRULY YOURS,

LARRY P. Puccetti
 (CUSTOMER SIGNATURE)

did not duplicate the
 and dimensions were
 gement; also, factory
 indicating no al-
 company. Trigger pull

ACCOUNT CHARGE

FORM 12825 REV. 5/77

Based on our findings, Remington Arms Company, Inc., cannot accept
 any liability or responsibility for the incident. It is possible that
 while your customer was moving the safety lever from the "safe" posi-
 tion to the "fire" position, he, at the same time, inadvertently con-
 acted the trigger. When the safety lever reached the "fire" position,
 the gun then discharged - as it is designed to do - because the trig-
 ger was being pulled with the gun no longer on "safe".