

April 26, 1994

Remington Arms Company
14 Hoefler Avenue
Ilion, New York 13357

Attention: Dennis Sanita

Dear Mr. Sanita:

On April 18, 1994, while participating in our monthly qualification program, my rifle experienced an abnormality that I had not incurred previously. While chambering a Federal 308 Winchester Match 168 grain Boat-tail hollow point, the bolt was placed in a closed position when the rifle discharged accidentally. My shooting finger was not in the trigger guard when this occurred.

This weapon was purchased in 1990 and approximately 550 to 600 rounds have been fired through it.

In the early stages, this weapon was experiencing a functioning problem with the bolt extracting empty brass casings. This was corrected by a new insertion of a retaining clip to the front bolt. This work was performed by Cherry Corners, 11136 Congress Road, Medina, Ohio, phone: 216-948-1238.

Your cooperation in this is greatly appreciated and time is of the essence in repair and return of this weapon as it is used by our Tactical Team.

Sincerely,

Gregory C. Varga

Gregory C. Varga
Range Officer
Brecksville Police
Department

(Phone: 216-526-8900)

* *Was offered to having him from used per Off. Varga during phone conv. 4/21*
GCV:etk



City of Brecksville

9069 BRECKSVILLE ROAD • BRECKSVILLE, OHIO 441
(216) 526-4351