

FIREARMSWOOD PRESS FORMINGMODEL 870, 12-16-20 GAUGE FORE-ENDS

Production reported that press formed Fore-ends are being produced on three shifts. The project for an additional set of presses and tooling is in Bridgeport for approval.

SHOTGUNSMODEL 3200 SHOTGUN
(Introduction 1973)

Production reported the following guns returned for modification through June 11:

	<u>Received</u>	<u>Shipped</u>	<u>In Process</u>
Shooter's Guns	2368	2207	161
Wholesaler's Guns	1055	1051	15
Guns Credited	1051		

An average of 17 guns per day were returned since May 20.

Marketing did make a new estimate of guns to be returned by quarter and costs for these modifications have been included in the #3 Forecast.

Marketing reported that modified guns are performing very well at major shoots. It is expected that about 12,000 guns will be sold this year - #3 Forecast.

Production reviewed modified guns that have been returned with complaints - Exhibit 1. Causes of "Fail to Fire" were: 1 - light indent; 3 - off-center blow; 2 - fail to cock; 4 - foreign material, and 3 - undefined. Reported under "Adjust Trigger Pull" were: 6 - preplay; 4 - creep, and 1 - pull weight. There was one recent complaint of "Fires on Closing"; however, it has not been possible to repeat this condition with the gun at Ilion. R & D will call this customer and if necessary, visit him to learn what he is doing and to see if he can duplicate the complaint.