

The Committee met Monday, November 22, 1971, from 2:59 to 3:27 p.m., to review the recall program to date. The following is a breakdown of the codes received at Bridgeport.

LU28W	-	1,600	rounds
LU29W	-	1,920	"
LU30W	-	0	"
LU31W	-	0	"
LU02ID	-	520	"
LU03ID	-	626	"
LU04ID	-	0	"

In codes other than LU03ID, each 100 rounds were 80 rounds bulk inspected and 20 rounds detail inspected. Code LU03ID rounds are all detail inspected.

Six Model 760 rifles are reported damaged and one Model 700 locked-up. There are possibly four or five more damaged guns. No personal injuries have been reported.

To date, 50 letters have been sent to distributors and approximately 10,000 to dealers.

83