

# REVIEW OF 5 mm R.. CARTRIDGES

## WRONG POWDER

	<u>Code</u>	<u>No. Of Boxes</u>	<u>S.S.</u>	<u>Defect</u> <u>Ballistic - Powder Weight</u>	<u>Received From</u>
3/72	X25D	42 (2100)	2/Box	2	Big Bear Stores Minot, N. Dakota
	X25D	40 (2000) /	2/Box	No defects	Melton Nashville, Tenn.
	X25D	40 (2000)	2/Box	No defects	Clearfield Hardware Clearfield, Penna.
	X25D	1	2/Box	No defects	Sloan's Sporting Goods Ridgefield, Conn.
	X24D	50 (2500)	2/Box	No defects	Geo. Lawrence Company Portland, Oregon
4/73	Y030	50 (2500)	2/Box	No defects	Bridgeport Warehouse
	X25D	6 (300)	2/Box	No defects	Stratton Terstegge Company Louisville, Kentucky
	X24D*	29 (1450)	2/Box	1	Gophers Shooter's Supply Farebault, Minnesota

\* See Complaint #12261 - Defects were reviewed and tubes scanned for codes.  
Conclusion that some of the 25th's production was packed in the "on hand"  
24th tubes..

Process Engineering  
JJCapasso:SFR  
7/9/73

WIL06597