3. Safety can be "tricked"; trigger connector remains disengaged from sear when moved to "safe" position and gun will fire when the lever is moved to "off" position - 4

- 3 -

 Trigger can be set in unsafe condition when safety lever is in "safe" position - 0

Production is rejecting guns which fall in the \$2, \$3, and \$4 categories. Indications are that this provides an ample safety factor that wear will not lead to the category \$4 situation during the life of the gun.

A gauge is being developed that will permit checking for sear lift at assembly.

Production is analyzing variations in purchased and internally manufactured parts and reviewing quality control procedures and limits. A list of recommendations for improving quality performance will be developed and reviewed by the Product Safety Committee.

A follow-up meeting is scheduled for the week of May 19.

T.J. Sharpe Secretary

Minima ve v