PRODUCT SAFETY SUBCOMMITTEE MEETING

-2-

OCTOBER 26, 1978

to Texas to review the replacement procedures being utilized by the recommended gunsmiths.

Production of any new Mohawk 600's is to be suspended so that 600 fire controls will be available for the recall correction. Available trigger assemblies will be allocated on a where-most-needed basis.

