

LIMITED DISTRIBUTION

PRODUCT SAFETY SUBCOMMITTEE MEETING
OCTOBER 30, 1978

PRESENT:

MINUTE #5 - 1978

SUBCOMMITTEE

OTHER

E. F. BARRETT, CHAIRMAN
J. G. WILLIAMS
R. A. PARTNOY
E. G. LARSON

J. E. PREISER
A. J. HERMANDORFER
W. L. PENN
H. D. ALBAUGH
H. K. BOYLE
J. H. CHISNALL
W. J. BOETTNER
R. B. SPERLING, ACTING SECRETARY

30-30 WIN. "ACCELERATOR"

It was reported that a small portion of a lot of about 400,000 "Accelerator" cartridges was loaded with double bullets, which could result in a high pressure explosion upon firing. 284,040 of the suspect code (July 19, 1978) have now been returned to our possession and 30,000 more were located in our warehouse. All distributors and dealers who received this ammunition have been notified and all have promised to return the applicable code. J. H. Chisnall is to follow up with the distributors and dealers. It is estimated that Remington will retrieve practically all of this suspect ammunition due to the fact that this was the initial production run of a new product and the product has not yet been disseminated in the field.

WIL06641