

OCTOBER 30, 1978

NYLON 66

It was reported that sixty-two Nylon 66 rifles were shipped from the Ilion plant with a misaligned sear cut which could lead to jar-offs. All sixty-two rifles shipped have been located in distributor inventories and are being returned. The shipment going to Remington Arms GmbH was caught prior to shipment. The Ilion plant will modify the gauges so that this problem cannot occur in the future.

PETERS MAGNUM #4 BUCKSHOT

It was reported that in July of 1977 some Peters Magnum #4 Buck Shotshells were loaded with 8523 Lot #5 powder which proved to have unacceptably low pressures in cold temperature testing. The pressures were sufficiently low to occasionally leave H wads in the barrel. The plant thought it had held all of suspect ammunition at time of production, but some must have been shipped. It was also reported that Burger Brothers of Edina, Minnesota had already taken out ads in local newspapers recalling this product from their customers.

The Subcommittee directed that tests be conducted to determine if there was any safety problem related to the leaving of an H wad in a barrel.

R. B. Sperling
Acting Secretary

RBS:hss

WIL06642