

(a copy of the letter is attached as Exhibit C). Preliminary examination shows that the Model 788, as well as several other models manufactured by competitors, are susceptible to having the safety moved from "safe" to "fire" by the fleshy part of the hand between thumb and forefinger when the gun is carried over the shoulder. Remington has had a few complaints about this situation in the past, but no reports of personal injury. The Subcommittee determined that the design of the Model 788 should be studied for corrective action, and that a letter of response should be prepared and sent to Mr. Burchard. (Subsequent to the meeting, a letter response was sent to Mr. Burchard--See copy attached as Exhibit D).

7mm EXPRESS CARTRIDGES

There have been reported incidents of gun damage due to consumers firing 7mm Express cartridges in firearms designed for magnum cartridges. The Marketing Manager (ammunition) and the Manager of Quality were directed to review the problem and recommend what could be placed on the 7mm Express containers that would re-emphasize the fact that the 7mm Express is not to be used in chambers designed for magnum loads.

30-06 HIGH PRESSURE LOADS

A recall notice was placed in vertical trade journals selected by Marketing as directed by the Product Safety Subcommittee in June, 1979. (See Exhibit E). Returns are no longer coming in pursuant to our notices. There still have been no complaints reported from