

the shell body obstruction. Examination of the fired rounds showed that this had occurred. In both instances, the inserted body cut off passed thru the bore with the shot column with no barrel damage.

EFS/ss  
Att.

*E. H. Lintner*

CONFIDENTIAL 83