

21MM Seismic - Returned Ammunition Evaluation

A report of the findings to date is attached as Exhibit "A". Testing is to continue to determine the cause of wads lodged in the barrel. A safety warning sheet is being developed for insertion in the packing case.

M/3200 Recall

Of the 305 guns involved in the recall for replacement of soft hammers, 151 (49.5%) have been returned and repaired. Procedures for handling the recall are in place and operating well and will continue to operate. This item will be dropped from the next agenda unless an abnormality occurs.

Product Safety Warnings

Ammunition Safety Warnings shown on Exhibit "B" were reviewed and agreed to be incorporated on all Center Fire packaging and all Shotshell packaging except 5 pack items. The packaging changeover will be made without obsolescence. About 1 year will be required for the changeover at the Plant level. Similar warnings will be developed for Rim Fire but space limitations on the package prohibit the use of warnings developed for Center Fire and Shotshell. Availability of manuals for older guns, as referred to in the warning, will be reviewed.