

REDACTED
PRIVILEGED

See MM008845

SAAMI - NSSF Safety Advertising

Copies of the four revised NSSF safety warnings were reviewed. The revisions reflect Remington's request that the four following areas be incorporated in the booklet and poster:

- obtain and read the Owner's Manual
- use proper cartridge or shell in the gun chambered for it
- periodic maintenance check of firearms
- never alter or modify a firearm

NSSF decided to incorporate them in the existing ten rather than adding four new items. A copy of the revised wording for the NSSF booklet and poster is attached as Exhibit "C". NSSF will incorporate the changes in the next printing run and new booklets will be used when current supplies are exhausted.

870 Competition Trap Gun

Firearms Research reported that a crack occurs occasionally at the rear of the ejection port. Tests were conducted to determine if this could develop into a safety hazard. Five guns were tested with one extremely high pressure round each to evaluate the severity of the resulting failures. The guns tested as follows: