

production sampling. The Chairman stated that this topic will be placed on the agenda for June or July 1982 to determine progress with the program.

Firearms

Model 870 "Competition Trap" Shotgun

The attached report details the tests conducted to determine the significance of cracked receivers in the subject firearm. In summary, receiver failures and safety features are no different than the standard Model 870 shotgun.


Policy for Dealing with Bolt Locks on Model 700 and Model 40X (B,C, & R) Firearms Returned for Repairs

There was discussion of procedures to be followed in repairing firearms with bolt locks. Since the absence or presence of a bolt lock is not a safety problem, determination of the policy to follow in these circumstances was not a matter for the Product Safety Subcommittee. 83

Miscellaneous

Minutes

Discussion focused on who should receive minutes of the meetings. After discussion, the Secretary was charged with preparing a proposal which will be reviewed and approved at the next meeting.


C. A. Nash, Secretary
Product Safety Subcommittee

CAN/kam

WIL06852