

- Marketing should contact selected warranty gunsmiths throughout the country and solicit their assistance in the Model Seven correction. Production should make available adequate supplies of new trigger assemblies. Ilion Research should prepare appropriate instructions for the gunsmiths on how to properly install the new trigger assemblies.
- Marketing should prepare, with the assistance from Public Relations and Legal, letters to Remington distributors and dealers requesting the return of the Model Seven and soliciting their aid in tracing gun owners. In addition, letters to gun owners requesting the return of the Model Seven to the nearest warranty gunsmith or to the Ilion Plant for correction, should be prepared by Marketing, with the assistance by Public Relations and Legal.
- A toll-free number should be established at Bridgeport to handle inquiries. 83

(Secretary's Note: Subsequent to this Meeting, the Executive Vice President and General Manager approved these recommendations.)

J. H. Chambers
J. H. Chambers
Secretary

JHC:hm