

Evaluation of product returned from several law enforcement agencies throughout the country, indicates that only about .02% of the suspect product that left the factory would be expected to fail to fire. While failure to fire does not normally pose a safety concern, a misfire of a service round being used by a law enforcement officer could be potentially dangerous. No accidents in connection with the use of the suspect lots have been reported.

The Subcommittee recommended to Management the following courses of action:

- All suspect product codes to continue on hold in the warehouses.
- Lonoke and Bridgeport plants will identify all customer shipments of the suspect codes for the period May through October, 1985.
- Suspect codes that have gone to law enforcement agencies, law enforcement suppliers, and full line wholesalers who sell to law enforcement agencies, will be recalled.
- Excise tax refund records will be reviewed to identify full line wholesalers who sell to law enforcement agencies.
- Law enforcement suppliers and full line wholesalers selling to law enforcement agencies who have received shipments of suspect codes will be contacted by Remington representatives to facilitate retrieval and